

<u>Drivability and leaks</u>	Repair all leaks and driveability concerns.	Active	oil pan installed	13.4
<u>Aerial Test</u>		Active		0
<u>UL Pump Certification</u>	Required as we are putting in a new pump	Active		0
<u>Loaner Fire Apparatus</u>	A similar capability fire apparatus will be made available at \$0 cost to the department throughout the duration of the refurbishment project.	Inactive		0
<u>Apparatus Pickup</u>	Customer will deliver apparatus to Brindlee Mountain. If pickup is required, arrangements can be negotiated and will be provided at cost only.	Inactive		0
<u>Apparatus Delivery</u>	Customer will pick-up apparatus once project is completed. If delivery is requested, arrangements can be negotiated and will be provided at cost only.	Inactive		0
<u>Sublet transport unit to shop</u>	due to breakdown inbound	Inactive		0
<u>Engine</u>	All perishable components replaced. Replace starter and alternator.	Completed	finished installing starter	13.85
<u>Transmission</u>	Check internal filters and adjust.	Completed	completed with service	0
<u>Front Suspension</u>	Inspect front suspension and quote rebuild if needed (springs, spring pins, U-bolts, shocks, and front axle alignment). Price includes alignment.	Completed	installed 2 new front shock,needs alignment	5.3
<u>Rear Suspension</u>	Inspect rear suspension and quote rebuild if needed (springs, torque rods, and rear axle alignment)	Completed	Inspected rear susp and springs,torque rods and axle in good condition.	0.85
<u>Axles, brakes and driveline</u>	1. Inspect brake system air valves and quote for needed repairs (air dryer, foot valve, relay valves, modulator valves, etc.) 2. Steer axle rebuild (brakes, drums, slack adjusters, cam bearings, kingpins, ABS sensors, hub bearings, hub seals and oil). ...	Completed	adjusted rear brakes, filled rear diff, verified operation of brakes.	72.65
<u>Replace lights to meet DOT requirements</u>	1. DOT lighting replacement (LED) 2. Warning light replacement (LED)	Completed	installed both rear rotators and spot lights and put truck back together	65.52
<u>Interior, compartment and panel lighting</u>	Install new LED lighting around step areas, ground, pump panel, and compartment lighting.	Completed	Install new LED lights on pump panel,all new ground lights and install all new LED lights in compartments	13.77
<u>Aerial Ladder Steps and Safety Measures</u>	Update safety control equipment on ladder steps and back of engine. Includes new handrails and positive grip steps.	Completed	Install new positive grip handrails and steps.	12.19
<u>STRINGER - Paint (Full)</u>	1. Exterior paint all red to match new engine (Repair body, re-prime, re-paint). 5. Interior compartments will be cleaned and painted as well with protective coating such as zolatone	Completed		0
<u>STRINGER - Paint (Partial)</u>	Repair, restore, and repaint existing compartment doors.	Completed		0
<u>FAB- Remove Bumper, weld holes in cab</u>	Remove front bumper/ weld holes in top of Cab	Completed	helped remove bumper, headliner and welding holes in roof	9.8
<u>FAB Replace Bumper chassis service</u>	Remove bent bumper and replace with new bumper. Cut holes in new bumper Fluid and filter service	Completed	Install new bumper and wiring lights on front bumper	14.4

<u>Drivability and leaks</u>	Repair all leaks and driveability concerns.	Active	oil pan installed	13.4
<u>Aerial Test</u>		Active		0
<u>UL Pump Certification</u>	Required as we are putting in a new pump	Active		0
<u>Loaner Fire Apparatus</u>	A similar capability fire apparatus will be made available at \$0 cost to the department throughout the duration of the refurbishment project.	Inactive		0
<u>Apparatus Pickup</u>	Customer will deliver apparatus to Brindlee Mountain. If pickup is required, arrangements can be negotiated and will be provided at cost only.	Inactive		0
<u>Apparatus Delivery</u>	Customer will pick-up apparatus once project is completed. If delivery is requested, arrangements can be negotiated and will be provided at cost only.	Inactive		0
<u>Sublet transport unit to shop</u>	due to breakdown inbound	Inactive		0
<u>Engine</u>	All perishable components replaced. Replace starter and alternator.	Completed	finished installing starter	13.85
<u>Transmission</u>	Check internal filters and adjust.	Completed	completed with service	0
<u>Front Suspension</u>	Inspect front suspension and quote rebuild if needed (springs, spring pins, U-bolts, shocks, and front axle alignment). Price includes alignment.	Completed	installed 2 new front shock,needs alignment	5.3
<u>Rear Suspension</u>	Inspect rear suspension and quote rebuild if needed (springs, torque rods, and rear axle alignment)	Completed	Inspected rear susp and springs,torque rods and axle in good condition.	0.85
<u>Axles, brakes and driveline</u>	1. Inspect brake system air valves and quote for needed repairs (air dryer, foot valve, relay valves, modulator valves, etc.). 2. Steer axle rebuild (brakes, drums, slack adjusters, cam bearings, kingpins, ABS sensors, hub bearings, hub seals and oil). ...	Completed	adjusted rear brakes, filled rear diff, verified operation of brakes.	72.65
<u>Replace lights to meet DOT requirements</u>	1. DOT lighting replacement (LED) 2. Warning light replacement (LED)	Completed	installed both rear rotators and spot lights and put truck back together	65.52
<u>Interior, compartment and panel lighting</u>	Install new LED lighting around step areas, ground, pump panel, and compartment lighting.	Completed	Install new LED lights on pump panel,all new ground lights and install all new LED lights in compartments	13.77
<u>Aerial Ladder Steps and Safety Measures</u>	Update safety control equipment on ladder steps and back of engine. Includes new handrails and positive grip steps.	Completed	Install new positive grip handrails and steps.	12.19
<u>STRINGER - Paint (Full)</u>	1. Exterior paint all red to match new engine (Repair body, re-prime, re-paint). 5. Interior compartments will be cleaned and painted as well with protective coating such as zolatone	Completed		0
<u>STRINGER - Paint (Partial)</u>	Repair, restore, and repaint existing compartment doors.	Completed		0
<u>FAB- Remove Bumper, weld holes in cab</u>	Remove front bumper/ weld holes in top of Cab	Completed	helped remove bumper, headliner and welding holes in roof	9.8
<u>FAB Replace Bumper chassis service</u>	Remove bent bumper and replace with new bumper. Cut holes in new bumper Fluid and filter service	Completed	Install new bumper and wiring lights on front bumper	14.4